



Vehicle History Report

Report Generated: 08-22-2022

[Copy Link](#) | [Download](#)



2014 Cadillac CTS 3.6L TT V-Sport Premium

VIN: 1G6AV5S83E0153570

Scan to open report:



Engine:

3.6L V6 DOHC 24V TWIN-TURBO

Drive Type:

RWD

Body Type:

SEDAN 4-DR

Transmission:

8-Speed Automatic

MSRP:

\$69,070

Country:

United States

A QUICK SUMMARY OF YOUR VEHICLE



State Title Brand Reported



Accident Reported (1). No Air Bag Deployed



No Other Damage Reported



Other Title Brand or Specific Event Reported



No Odometer Problem(s) Reported



Open Recall(s) Reported (1)



Service & Repair Information Reported



Number of Owners

Calculated Owners: 2

Purchased: 2014

Location: MT

Own from: 06/01/2014 - 11/02/2019

Duration: 5 year(s) 5 month(s)

Purchased: 2019

Location: CA

Own from: 11/02/2019 - 01/24/2020

Duration: 2 month(s)



Vehicle Use: There is indication of the below usage(s) for this vehicle

[Personal](#) | Fleet | Rental | Lease | Taxi | Livery | Police | Government | Drivers Ed | Commercial

Window Sticker

Learn more with a Window Sticker

The sticker on the window is a rich source of essential information about your automobile. The window sticker lets your buyer know exactly what's included particularly in your car.

[Sample Window Sticker](#)

[Order Window Sticker](#)





 Runs & Drives |  Engine Starts |  Has Keys

Sale Status

\$4,150 Sold

SOLD

Auction Info

Auction Type	Pure Sale
Seller Type	Insurance Company
Auction Date	February 5, 2020 2:00 PM CST
Location	Martinez, California

Vehicles Sales History

2 years ago	Sold (This listing)
-------------	---------------------

Title & Condition

Title Type	Salvage
Title Description	CA - Salvage Certificate
Primary Damage	Front End
VIN	1G6AV5S83E0153570

Technical Specs

Odometer :	88,160 actual miles3,875 less than average
Avg. Estimated Retail Value :	\$24,421
Estimated Winning Bid :	\$4,141 - \$6,212
Body Style :	Sedan
Color :	Silver
Engine Type :	3.6L 6
Fuel Type :	Gas
Cylinders :	6
Transmission :	Automatic
Drive :	Rear-Wheel Drive



Runs & Drives

Engine Starts

Has Keys

Sale Status

\$7,700 Sold

SOLD

Auction Info

Auction Type	Minimum Bid
Seller Type	Third Party
Auction Date	July 13, 2020 2:00 PM CDT
Location	Los Angeles, California
Buyer Country	Mexico

Vehicles Sales History

Jul 9, 2020	Seller declined \$8,700
Jun 15, 2020	Seller declined \$8,400
Jun 11, 2020	Seller declined \$8,700
Jun 8, 2020	Seller declined \$7,600
Jun 4, 2020	Seller declined \$10,200
Jun 1, 2020	Seller declined \$10,200
May 28, 2020	Seller declined \$10,700
May 22, 2020	Seller declined \$8,600
May 21, 2020	Seller declined \$8,900
May 18, 2020	Seller declined \$8,900
2 years ago	Lot sold for \$4,150

Title & Condition




Title Type	Salvage
Title Description	CA - Salvage Certificate (P)
Primary Damage	Front End
VIN	1G6AV5S83E0153570

Technical Specs

Odometer :	88,160 actual miles3,875 less than average
Avg. Estimated Retail Value :	\$24,421
Estimated Winning Bid :	\$4,141 - \$6,212
Body Style :	Sedan
Color :	Silver
Engine Type :	3.6L 6
Fuel Type :	Gas
Cylinders :	6
Transmission :	Automatic
Drive :	Rear-Wheel Drive

STATE / TITLE BRAND VERIFICATION











1 Problem(s) Reported	Major State Title Areas Checked
✓	No fire brand
✓	No hail brand
✓	No flood brand
✓	No junk or scrapped brand
✓	No manufacturer buyback
✓	No lemon brand

1 Problem(s) Reported	Major State Title Areas Checked
	Salvage brand
	No rebuilt or rebuildable brand
	No odometer brand (EML or NAM)










ACCIDENT INFORMATION

Accident Number	Date of Accident	Location
1	04/02/2020	CA

DAMAGE VERIFICATION

0 Problem(s) Reported	Other Problem Areas Checked
	No non-title fire damaged record
	No non-title hail damaged record
	No non-title flood damaged record
	No auction junk or scrapped record
	No auction rebuilt or rebuildable record
	No salvage auction record
	No damaged or major damage incident record
	No structural damage or structural alteration record
	No recycling facility record
	No crash test record

ODOMETER VERIFICATION

0 Problem(s) Reported	Mileage	Date Reported
	10 mi	06/26/2014
	7,162 mi	07/24/2014
	85,748 mi	09/17/2019
	85,783 mi	10/17/2019
	88,160 mi	12/19/2019
	88,160 mi	01/22/2020
	88,275 mi	09/03/2020
	110,110 mi	03/03/2022
	111,109 mi	03/15/2022

INSPECTION RECORDS











No Inspection Records Found.

SERVICE & REPAIR INFORMATION

--

Date of Service	Location	Source	Service Type
07/24/2014	MT	Service Contract Company	SERVICE CONTRACT REPAIR PERFORMED
09/06/2016	MT	Dealer Service	STEERING SYSTEM SERVICEDCOOLING SYSTEM SERVICEDMULTIPLE POINT VEHICLE INSPECTIONVEHICLE DETAILEDSPUSPENSION SERVICEDTIRES OR WHEELS SERVICE PERFORMEDLUBE, OIL AND/OR FILTER CHANGEDVEHICLE FLUIDS SERVICEDPROMOTIONAL SERVICE PERFORMED
09/29/2016	MT	Dealer Service	STEERING SYSTEM SERVICEDCOOLING SYSTEM SERVICEDMULTIPLE POINT VEHICLE INSPECTIONSUSPENSION SERVICEDVEHICLE FLUIDS SERVICEDPROMOTIONAL SERVICE PERFORMED
01/18/2017	MT	Dealer Service	COOLING SYSTEM SERVICEDMULTIPLE POINT VEHICLE INSPECTIONTIRES OR WHEELS SERVICE PERFORMEDLUBE, OIL AND/OR FILTER CHANGEDVEHICLE FLUIDS SERVICEDPROMOTIONAL SERVICE PERFORMED
02/03/2017	MT	Dealer Service	COOLING SYSTEM SERVICEDMULTIPLE POINT VEHICLE INSPECTIONVEHICLE FLUIDS SERVICEDPROMOTIONAL SERVICE PERFORMED
03/06/2017	MT	Dealer Service	COOLING SYSTEM SERVICEDMULTIPLE POINT VEHICLE INSPECTIONVEHICLE FLUIDS SERVICEDPROMOTIONAL SERVICE PERFORMED
03/15/2017	MT	Dealer Service	COOLING SYSTEM SERVICEDMULTIPLE POINT VEHICLE INSPECTIONVEHICLE DETAILEDVEHICLE FLUIDS SERVICEDPROMOTIONAL SERVICE PERFORMED
08/03/2017	MT	Dealer Service	COOLING SYSTEM SERVICEDMULTIPLE POINT VEHICLE INSPECTIONBRAKES SERVICEDLUBE, OIL AND/OR FILTER CHANGEDVEHICLE FLUIDS SERVICEDPROMOTIONAL SERVICE PERFORMED
08/17/2017	MT	Dealer Service	STEERING SYSTEM SERVICEDCOOLING SYSTEM SERVICEDMULTIPLE POINT VEHICLE INSPECTIONBRAKES SERVICEDSPUSPENSION SERVICEDVEHICLE FLUIDS SERVICEDPROMOTIONAL SERVICE PERFORMED

EVENT VERIFICATIONS

2 Event(s) Reported	Vehicle Events Checked
	No Insurance Loss record
	Titled to an insurance company record
	No Auction Lemon/Manufacturer Buyback record
	No abandoned title record
	No grey market title record
	Loan/Lien record(s)
	No repossessed record
	No corrected title record
	No duplicate title record
	No theft record(s)

DETAILED HISTORY VERIFICATION

Event Date	Location	Odometer Reading	Data Source	Details
06/01/2014	GREAT FALLS, MT		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL

Event Date	Location	Odometer Reading	Data Source	Details
06/26/2014	GREAT FALLS, MT	10 mi	Motor Vehicle Dept.	TITLE(TITLE #:AA2167349) (LIEN REPORTED)
07/24/2014	BILLINGS, MT	7,162 mi	Service Contract Company	SERVICE CONTRACT REPAIR PERFORMED
06/01/2015	GREAT FALLS, MT		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
06/01/2016	GREAT FALLS, MT		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
09/06/2016	BILLINGS, MT		Dealer Service	STEERING SYSTEM SERVICED COOLING SYSTEM SERVICED MULTIPLE POINT VEHICLE INSPECTION VEHICLE DETAILED SUSPENSION SERVICED TIRES OR WHEELS SERVICE PERFORMED LUBE, OIL AND/OR FILTER CHANGED VEHICLE FLUIDS SERVICED PROMOTIONAL SERVICE PERFORMED
09/29/2016	BILLINGS, MT		Dealer Service	STEERING SYSTEM SERVICED COOLING SYSTEM SERVICED MULTIPLE POINT VEHICLE INSPECTION SUSPENSION SERVICED VEHICLE FLUIDS SERVICED PROMOTIONAL SERVICE PERFORMED
01/18/2017	BILLINGS, MT		Dealer Service	COOLING SYSTEM SERVICED MULTIPLE POINT VEHICLE INSPECTION TIRES OR WHEELS SERVICE PERFORMED LUBE, OIL AND/OR FILTER CHANGED VEHICLE FLUIDS SERVICED PROMOTIONAL SERVICE PERFORMED
02/03/2017	BILLINGS, MT		Dealer Service	COOLING SYSTEM SERVICED MULTIPLE POINT VEHICLE INSPECTION VEHICLE FLUIDS SERVICED PROMOTIONAL SERVICE PERFORMED
03/06/2017	BILLINGS, MT		Dealer Service	COOLING SYSTEM SERVICED MULTIPLE POINT VEHICLE INSPECTION VEHICLE FLUIDS SERVICED PROMOTIONAL SERVICE PERFORMED
03/15/2017	BILLINGS, MT		Dealer Service	COOLING SYSTEM SERVICED MULTIPLE POINT VEHICLE INSPECTION VEHICLE DETAILED VEHICLE FLUIDS SERVICED PROMOTIONAL SERVICE PERFORMED
06/01/2017	GREAT FALLS, MT		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
08/03/2017	BILLINGS, MT		Dealer Service	COOLING SYSTEM SERVICED MULTIPLE POINT VEHICLE INSPECTION BRAKES SERVICED LUBE, OIL AND/OR FILTER CHANGED VEHICLE FLUIDS SERVICED PROMOTIONAL SERVICE PERFORMED
08/17/2017	BILLINGS, MT		Dealer Service	STEERING SYSTEM SERVICED COOLING SYSTEM SERVICED MULTIPLE POINT VEHICLE INSPECTION BRAKES SERVICED SUSPENSION SERVICED VEHICLE FLUIDS SERVICED PROMOTIONAL SERVICE PERFORMED

Event Date	Location	Odometer Reading	Data Source	Details
06/01/2018	MISSOULA, MT		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
06/01/2019	MISSOULA, MT		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
09/17/2019	CA	85,748 mi	Motor Vehicle Dept.	PASSED EMISSION INSPECTION
10/17/2019	CA	85,783 mi	Motor Vehicle Dept.	ODOMETER READING FROM DMV
10/18/2019	UKIAH, CA		Dealer Record	VEHICLE IN DEALER INVENTORY
11/02/2019	UKIAH, CA		Motor Vehicle Dept.	TITLE(LIEN REPORTED) REGISTRATION EVENT/RENEWAL
12/19/2019	PACIFIC SW REGION	88,160 mi	Auto Auction	REPORTED AT AUTO AUCTION
01/22/2020	CA	88,160 mi	Motor Vehicle Dept.	ODOMETER READING FROM DMV
01/24/2020	CA		Motor Vehicle Dept.	TITLE SALVAGE VEHICLE TITLED/REGISTERED TO AN INSURANCE COMPANY
04/02/2020	CA		State Agency	ACCIDENT REPORTED, EVENT DATE IS DATE REPORTED TO AUTOCHECK
09/03/2020	CA	88,275 mi	Motor Vehicle Dept.	ODOMETER READING FROM DMV
09/03/2020	CA		Motor Vehicle Dept.	PASSED EMISSION INSPECTION
09/04/2020	ORANGE COVE, CA		Motor Vehicle Dept.	TITLE REGISTRATION EVENT/RENEWAL
09/04/2020	ORANGE COVE, CA		Motor Vehicle Dept.	SALVAGE
03/03/2022	MODESTO, CA	110,110 mi	State Agency	EMISSION INSPECTION
03/15/2022	MODESTO, CA	111,109 mi	State Agency	EMISSION INSPECTION

Recall Date	MFR Recall Number	Component
01/23/2020	Safety	N192279370

This Detailed Vehicle History Report is based only on information acquirable by Detailed Vehicle History as at the time of generating this report. Note that other information about this vehicle, including problems and services, may not have been reported to Detailed Vehicle History. You are strongly advised to use this report only as an additional but important tool, along with the vehicle inspection and test drive, to make an informed decision about the purchase of this vehicle. © 2022 [Detailed Vehicle History](#). All Rights Reserved.