



# Vehicle History Report

Report Generated: 09-05-2022

[Copy Link](#) | [Download](#)



Mercedes-Benz

## 2017 Mercedes-Benz GLA GLA 250 4MATIC

VIN: WDCTG4GBXHJ280727

Scan to open report:



### Engine:

L4, 2.0L, DOHC 16V, Turbo

### Transmission:

Automatic

### MSRP:

\$34,850

### Vehicle Type:

MPV

### Fuel Type:

Gasoline

### Drive Type:

AWD

### Body Type:

4 Door Hatchback

### Country:

Germany

## A QUICK SUMMARY OF YOUR VEHICLE



State Title Brand Reported



Accident Reported (1). No Air Bag Deployed



No Other Damage Reported



Other Title Brand or Specific Event Reported



No Odometer Problem(s) Reported



No Open Recall(s) Reported



Service & Repair Information Reported



### Number of Owners

Calculated Owners: 1

**Purchased:** 2017

**Location:** CA

**Own from:** 03/08/2017 - 04/06/2020

Duration: 3 year(s)



Vehicle Use: There is indication of the below usage(s) for this vehicle

Personal | Fleet | Rental | [Lease](#) | Taxi | Livery | Police | Government | Drivers Ed | Commercial

## Window Sticker

### Learn more with a Window Sticker


The sticker on the window is a rich source of essential information about your automobile. The window sticker lets your buyer know exactly what's included particularly in your car.

[Sample Window Sticker](#)

[Order Window Sticker](#)



AUCTION RECORDS



Runs & Drives

☐ Engine Starts

Has Keys

Sale Status

\$4,950 Sold

SOLD

Auction Info

Auction Type	Pure Sale
Seller Type	Insurance Company
Auction Date	April 13, 2020 2:00 PM CDT
Location	Sacramento, California
Buyer Country	United States

Vehicles Sales History

No previous auction found!

Title & Condition

Title Type	Salvage
Title Description	CA - Salvage Certificate
Primary Damage	Front End
VIN	WDCTG4GBXHJ280727

Technical Specs

Odometer :	10,931 actual miles44,140 less than average
Estimated Repair Cost :	\$27,458
Avg. Estimated Retail Value :	\$27,582
Damage Ratio :	102%
Estimated Winning Bid :	\$4,804 - \$5,872
Body Style :	Hatchback
Color :	Brown
Engine Type :	2.0L 4
Fuel Type :	Gas
Cylinders :	4
Transmission :	Automatic
Drive :	All Wheel Drive
City Mileage :	23 miles/gallon
Delivery Charges :	\$925
Highway Mileage :	31 miles/gallon
Standard Seating :	5
Engine Size :	2 Liters
Vehicle Style :	SUV (4-Door)
Engine :	2.0L L4 DOHC 16V TURBO
Made In :	Germany
Vehicle Size :	Compact
Overall Length :	173.90 inches
Steering Type :	R&P
Anti-Brake System :	4-Wheel ABS
Fuel Capacity :	13.2 gallon
Overall Height :	60.00 inches
Doors :	4
Curb Weight :	3428
Trim :	GLA250 4MATIC
Overall Width :	71.00 inches
Transmission Gears :	7

STATE / TITLE BRAND VERIFICATION

1 Problem(s) Reported	Major State Title Areas Checked
✓	No fire brand
✓	No hail brand
✓	No flood brand
✓	No junk or scrapped brand

1 Problem(s) Reported	Major State Title Areas Checked
✓	No manufacturer buyback
✓	No lemon brand
⚠	Salvage brand
✓	No rebuilt or rebuildable brand
✓	No odometer brand (EML or NAM)

#### ACCIDENT INFORMATION

Accident Number	Date of Accident	Location
1	07/01/2021	CA

#### DAMAGE VERIFICATION

0 Problem(s) Reported	Other Problem Areas Checked
✓	No non-title fire damaged record
✓	No non-title hail damaged record
✓	No non-title flood damaged record
✓	No auction junk or scrapped record
✓	No auction rebuilt or rebuildable record
✓	No salvage auction record
✓	No damaged or major damage incident record
✓	No structural damage or structural alteration record
✓	No recycling facility record
✓	No crash test record

#### ODOMETER VERIFICATION

0 Problem(s) Reported	Mileage	Date Reported
✓	10 mi	09/09/2016
✓	88 mi	02/23/2017
✓	585 mi	04/19/2017
✓	3,703 mi	02/16/2018
✓	10,931 mi	02/17/2020
✓	10,931 mi	03/31/2020
✓	11,111 mi	08/15/2020
✓	11,100 mi	08/15/2020

#### INSPECTION RECORDS

No Inspection Records Found.
------------------------------

#### SERVICE & REPAIR INFORMATION

--

Date of Service	Location	Source	Service Type
09/09/2016	CA	Independent Repair Center	MULTIPLE POINT VEHICLE INSPECTIONVEHICLE DETAILED
02/27/2017	CA	Independent Repair Center	BATTERY SERVICED OR REPLACEDMULTIPLE POINT VEHICLE INSPECTIONVEHICLE DETAILEDTIRES OR WHEELS SERVICE PERFORMED
04/19/2017	CA	Independent Repair Center	BATTERY SERVICED OR REPLACEDTIRES OR WHEELS SERVICE PERFORMED
02/16/2018	CA	Independent Repair Center	TIRES OR WHEELS SERVICE PERFORMED

EVENT VERIFICATIONS

2 Event(s) Reported	Vehicle Events Checked
✓	No Insurance Loss record
i	Titled to an insurance company record
✓	No Auction Lemon/Manufacturer Buyback record
✓	No abandoned title record
✓	No grey market title record
i	Loan/Lien record(s)
✓	No repossessed record
✓	No corrected title record
✓	No duplicate title record
✓	No theft record(s)

DETAILED HISTORY VERIFICATION

Event Date	Location	Odometer Reading	Data Source	Details
09/09/2016	CA	10 mi	Independent Repair Center	MULTIPLE POINT VEHICLE INSPECTION VEHICLE DETAILED
02/23/2017	CA	88 mi	Motor Vehicle Dept.	ODOMETER READING FROM DMV
02/27/2017	CA		Independent Repair Center	BATTERY SERVICED OR REPLACED MULTIPLE POINT VEHICLE INSPECTION VEHICLE DETAILED TIRES OR WHEELS SERVICE PERFORMED
03/08/2017	CA		Motor Vehicle Dept.	TITLE(LEASED VEHICLE)(LIEN REPORTED) REGISTRATION EVENT/RENEWAL(LEASED VEHICLE)
04/19/2017	CA	585 mi	Independent Repair Center	BATTERY SERVICED OR REPLACED TIRES OR WHEELS SERVICE PERFORMED

Event Date	Location	Odometer Reading	Data Source	Details
02/16/2018	CA	3,703 mi	Independent Repair Center	TIRES OR WHEELS SERVICE PERFORMED
02/17/2020	PACIFIC SW REGION	10,931 mi	Auto Auction	REPORTED AT AUTO AUCTION
03/31/2020	CA	10,931 mi	Motor Vehicle Dept.	ODOMETER READING FROM DMV
04/06/2020	SACRAMENTO, CA		Motor Vehicle Dept.	TITLE SALVAGE VEHICLE TITLED/REGISTERED TO AN INSURANCE COMPANY
08/15/2020	SACRAMENTO, CA	11,111 mi	Motor Vehicle Dept.	TITLE REGISTRATION EVENT/RENEWAL
08/15/2020	SACRAMENTO, CA		Motor Vehicle Dept.	SALVAGE
08/15/2020	CA	11,100 mi	Motor Vehicle Dept.	PASSED EMISSION INSPECTION
07/01/2021	CA		State Agency	ACCIDENT REPORTED, EVENT DATE IS DATE REPORTED TO AUTOCHECK

RECALLS

No Recalls found.

*This Detailed Vehicle History Report is based only on information acquirable by Detailed Vehicle History as at the time of generating this report. Note that other information about this vehicle, including problems and services, may not have been reported to Detailed Vehicle History. You are strongly advised to use this report only as an additional but important tool, along with the vehicle inspection and test drive, to make an informed decision about the purchase of this vehicle. © 2022 [Detailed Vehicle History](#). All Rights Reserved.*